

Data Submitted (UTC 11): 10/1/2025 1:06:15 AM

First name: Kenneth

Last name: Meyer

Organization:

Title:

Comments: I worked for the Gifford Pinchot from 1997 to 2023. During that time there were several occasional when the current tunnel needed to be repaired. In addition, instability in the ridge above the current out severely damaged Highway 504 and threaten to block the out flow of the tunnel.

I would favor alternatives that provide an outflow in a more stable location.