




Ewing Mountain Erosion Hazard Compartment 4970




Ewing Mountain Erosion Hazard Compartment 4971



Ewing Mountain Erosion Hazard Compartment 4972




Ewing Mountain Erosion Hazard Compartment 4973



Map created by: Miller Cochran (mcochran@selcnc.org) | Last updated: May 27, 2021
Sources: USDA-NRCS gSSURGO, USDA-ES

Sources: USDA-NRCS gSSURGO, USDA-FS,

Ewing Mountain Erosion Hazard Compartment 4974




Map created by: Miller Cochran (mcochran@selcnc.org) | Last updated: May 27, 2021
Sources: USDA-NRCS gSSURGO, USDA-ES


Sources: USDA-NRCS gSSURGO, USDA-FS,

- Proposed Treatment Blocks
- Moderate Potential Erosion Hazard (Road/Trail)
- Severe Potential Erosion Hazard (Road/Trail)
- Moderate or Severe Potential Erosion Hazard (Road/Trail) and Slope $\geq 35\%$


Ewing Mountain Erosion Hazard Compartment 4976



Ewing Mountain Erosion Hazard Compartment 4977




Ewing Mountain Erosion Hazard Compartment 4978




 SOUTHERN
ENVIRONMENTAL
LAW CENTER
4977

Map created by: Miller Cochran (mcochran@selcnc.org) | Last updated: May 27, 2021
Sources: USDA-NRCS gSSURGO, USDA-FS


Ewing Mountain Erosion Hazard Compartment 4979



Ewing Mountain Erosion Hazard Compartment 4983



Ewing Mountain Erosion Hazard Compartment 4984



Map created by: Miller Cochran (mcochran@selcnc.org) Last updated: May 27, 2021

Sources: USDA-NRCS gSURGO, USDA-FS

4975