

Data Submitted (UTC 11): 9/14/2022 3:13:28 AM

First name: Collin

Last name: Neuhauser

Organization:

Title:

Comments: I have some concerns about the Granite Creek area of the project North of Clover Meadow.

1. The map shows the strawberry mine in the wrong location. The 2022 visitor map has the corrected location for reference. The WUI buffer for the mine area is also in the wrong location.

2. I am unsure why the project area North and East of Granite Creek campground is not more inclusive. There is needed work along the entire 5s30 corridor. The road is very likely to wash out in a winter storm and needs to have the creek banks armored. The project boundary as currently drawn in that area makes very little sense.

I also have a concern for the entire project:

Is the project taking into account current road conditions when making management decisions? Examples include the missing portion of 5S13 and the multiple road failures on 6s22Y