

Data Submitted (UTC 11): 3/3/2023 5:48:58 PM

First name: Anon

Last name: Anon

Organization:

Title:

Comments: Additional vault toilet facilities should be included in project scope and outside of the campground to ensure waste is properly disposed. Suggest one at hill base near the refuge and one up top. Repairing the ENTIRE road network is imperative to ensuring public access for hiking and hunting. The network is a great asset to visitors and locals alike. Recommend repairing the 1mi to Goodwin instead of shutting it off if already doing other road repairs - its frustrating to see old roads shut down access to locations in the BTNF. What's to stop the road from continuing to get shorter? Perhaps requiring UTVs and ATVs to pay a permit fee directly applicable to road maintenance would help.