

Data Submitted (UTC 11): 9/26/2024 4:42:29 PM

First name: Michael

Last name: Blakeslee

Organization:

Title:

Comments: Not allowing the replacement of the two lifts at Sunlight is rediculous at best and potentially negligent at worst. For the lift operators and lift mechanics to be required to work on equipment that is 60 to 70 years old is dangerous. Is there anyone in this country still working on or maintaining any machinery that is older than 20 to 25 years old? The people who maintain these lifts are basically performing miracles every year to keep these relics operational. They shouldn't have to be. Safety of employees and guests is always the main concern and these lifts skirt the edges of what is acceptable . Considering that the manufacturer of the lifts (Riblet) is out of business it will not be long before parts will not be available.