

Data Submitted (UTC 11): 1/27/2025 3:47:48 PM

First name: Brian

Last name: Mckenzie

Organization:

Title:

Comments: This would be the ideal time to upgrade Forest Service road 1S23 from Horse Ridge lookout to the intersection with 29N30 to a gravel maintained road with drainage. As it is it erodes every winter with the rains. No cross slope or water bars in most areas and a mud pit with every rain not to mention the brush encroaching nearly 5' into the roadway on both sides. This is a main connector loop across Southfork that has a lot of traffic during the summer and the fall hunting season. The road maintenance in most all of Six Rivers N/F is almost nonexistent.