

Data Submitted (UTC 11): 1/22/2023 10:26:19 PM

First name: Bonnie

Last name: Weathers

Organization:

Title:

Comments: REASONS WHY NOT TO PUT A GRAVEL PIT MINE AND ROCK CRUSHING OPERATION ON FSR 738, JUST OFF FSR 37-JACKSON MOUNTAIN ROAD

1. Homes in San Juan River Village are less than 2000 ft away
2. Located near newly planned site for a mountain bike trail system
3. Uncontrollable DUST in the air for the existing homes, residents and their visitors, and visitors of their family and friends, not to mention there are already existing residents that bought homes and moved here to escape a dust problem
4. We are and have been a PRIVATE and QUIET neighborhood since its inception, and do NOT wish to change that.
5. Hwy 160 is an already heavily travelled road in summer and winter, for back-country hiking, skiing, back-country adventures, as well as an only entrance/exit for Mineral County residents and others to get to Pagosa Spgs, Durango and beyond. Of course Hwy 160 also is the only way for Archuleta County residents to get to Mineral County and beyond.

Bonnie Weathers

Property owner since 1999, Full-time resident since 2006