

Data Submitted (UTC 11): 1/21/2025 8:45:18 PM

First name: Kevin

Last name: McNitt

Organization:

Title:

Comments: How will the Flag Mtn Road rebuild affect the snowmobile trail system? Will you be maintaining enough cover to ensure the road holds snow in the winter or will the trail be rerouted to areas that will maintain canopy cover to protect the snow. How will the thinning and over canopy be handled, there are areas North East of Deerfield lake off of Slate Prairie road in the Rimmer canyon area where all of the over canopy was removed allowing for an explosion of growth of jack pines that are impossible to pass through which has affected the hunting opportunities in that area. The skidder trails are the only passable area for hunters and wildlife and the entire area looks unsightly. The entire area looks like a ski slope.