

Data Submitted (UTC 11): 9/5/2019 7:00:00 AM

First name: Paul

Last name: Loutzenhiser

Organization: 4wd recreational user group

Title:

Comments: This my public comment for the Buckskin project. It will represent 2 user groups.

1. As a Hunter, the forest needs more controlled burns, specifically around the Packsaddle mountain area. Trail 76 is severally rutted and needs significant work. The 1050 road needs a fair amount of work towards the last 4 miles of it. Also in the 1050E is severally over grown and needs to be brushed out.

2. As a representative of the 4wd recreational user group. We would like to see 15-20 miles of a trail Class 2 for greater than 50" 4wd's with 36" obstacles

through out the system. With the logging, burning, and the NEPA study already going on. This should be straight forward to accomplish.

3. (Attached) Here are the specifications for the trail system from the USFS if you didn't know where to find them.

Thank you

Paul Loutzenhiser