




Unstable Soils and Project Stands


North Fork Stillaguamish Landscape Analysis Project



Map 2: Identified highly unstable areas. Red and purple areas are high risk areas that would not receive treatments or new road cuts in this project.



Soil Resource Inventory (SRI) Natural Stability and Project Stands North Fork Stillaguamish Landscape Analysis Project



Map 3: SRI layers were categorized as High, Moderate, and Low risks of stability. Timber stands that are located in areas that are yellow-Moderately stable and areas that are not rated will have a survey done prior to treatment implementation.

No timber stands are proposed for Orange/ Red – Unstable/ Highly Unstable areas.