SUUIN DANUIA WAIEN			U7-9Z
Location Nw 45w 4 Sec 30 Twp ZN Rg 5E  County  North	Well Owner: John + Arnis Business Name:	Kny	TSON
Penn	Address: 20920 Knutson Rd Quinn 50 57775		
Please mark well location with an "X"	WELL LOO		
W - E		DEPTH FROM TO	
X	FORMATION	<del></del>	TO
Well-Completion Date	topsoil	0	2
	Rotten Schist	2	6
10-20-09 - 1 Mile ->	mice Schist	6	85
LOCATION:			
Distance from nearest potential pollution source (septic tank, abandoned well, feed lot, etc.)?ft. from Nove Cluse (identify source)			
		1	
PROPOSED USE:  ☑ Domestic/Stock ☐ Municipal ☐ Business ☐ Test Holes		<del> </del>	
☐ Irrigation ☐ Industrial ☐ Institutional ☐ Monitoring well		†	<del></del>
METHOD OF DRILLING:		<u> </u>	L
	STATIC WATER LEVEL 40		Fed
AIR RUTARY	If flowing: closed in pressure		
CASING DATA: Steel 🛭 Plastic 🔲 Other	GPM flowthrough		
lf other describe	Controlled by Valve Reducers Othe		
PIPEWEIGHT DIAMETER FROM TO HOLE DIAMETER	Reduced FlowrateGF		
160 LB/AFT 6 IN 0 FT 30 FT 81/2 IN	Can well be completely shut in?		
LB/FTINFTIN	WELL TEST DATA.		
LB/FTINFTFTIN	Describe: Blace	wit	Lain
GROUTING DATA	Railed		
Grout Type No. of Sacks Grout Weight From To	Other		
	<b>!</b>		
Describe grouting procedure pumped sement down		16	GPN
Tremie tube from Rollom up	ft. AfterHrs. pumped _		GPN
SCREEN: Perforated pipe Manufactured	If pump installed, pump rate		GPN
DiameterIN LengthFEET	REMARKS REC	EIVED	
Material			
Slot Size Set From Feet toFeet	NOV - 5 2009		
Other information		ER RIGHTS LOGRAM	
	This well was drilled under license #		
WAS A PACKER OR SEAL USED? ☑ YES ☐ NO	And this report is true and accurate.		
If so, what material? Ruffer	Drilling firm Hamm Dailli.	19	
Describe packer(s) and location? Fland Butha 30 ft	Signature of License Representative:	/	
DISINFECTION: Was well disinfected upon completion?	Vaugles He	mm	
	Signature of Well Owner or Equitable Property Holder	r:	
Laboratory sent to for waterNO, Why Not?quality analysis	-		
	1. 11. 2- 60		
	Date:		